



# Set Up Instructions For 8-1/2 x 11 Counter Display SDC-40





1. Square up Counter Display as shown. Fold bottom and front flaps on sides as shown. Fold side flaps over and lock tabs into back of display.




2. Fold side flaps on floor of display as shown. Fold front of display up and over front flaps. Push floor of display securely down into display.

3. Carefully bend support in rear of display out as shown. Insert support into rear of display as shown.



*IF OPTIONAL HEADER IS USED...*

Insert header down into display as shown.



*IF USED AS A HANGING DISPLAY...*

Insert hook into corresponding slots in rear of display and hang as desired.

Note: Do not open support if used as a Hanging Display